United States of America

Department of Transportation—Jederal Aviation Administration

Supplemental Type Certificate

Number SASSSSW

P/N 190-714

This certificate, issued to Falcon Jet Corporation P.O. Box 967

Little Rock, Arkansas 72203

certifies that the change in the type design for the following product with the limitations and conditions

therefor as specified hereon meets the airworthiness requirements of Part 4b of the Civil Air

Regulations.

Original Product - Type Certificate Number: ATEU

Make: Avions Marcel Dassault - Brequet

Model: Fan Jet Falcon; Fan Jet Falcon Series D,

Fan Jet Falcon Series E

Description of Type Design Change:

Installation of Wing Pylons and Underwing Stores in accordance with Falcon Jet Report No. F20-01043, Revision Z dated June 17, 1987, or later FAA approved revision.

Limitations and Conditions:

See Continuation Sheet, page 2, of this STC.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 11, 1984

Date reissued:

Date of issuance:

December 21, 1984

Date amended: 5/6/85; 11/1/85; 7/16/86; 1/27/87; 10/13/87 Revision 5 By direction of the Administrator



allaunnes

L. B. Andriesen (Signature)
Manager, Aircraft Certification Division

Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

(Continuation Sheet)

Number SA5858SW

Revision 5

Limitations and Conditions:

- 1. FAA Approved Airplane Flight Manual Supplement Report No. 35629-1 dated 12/21/84, is required with installation according to Drawing List F20-01043, Revision B dated 12/20/84; or Supplement Revision B dated 5/6/85, is required with installation (-501) according to Drawing List F20-01043, Revision G dated 5/2/85; Supplement Revision I dated 11/1/85, is required with installation (-503) according to Drawing List F20-01043, Revision K dated 9/25/85; or Supplement Revision L dated 7/16/86, is required with installation (-505) according to Drawing List F20-01043, Revision W dated 6/5/86; or Supplement Revision M dated 1/21/87, is required with installation in accordance with Drawing List F20-1043, Revision X dated 6/7/86; or Supplement Revision N dated 1/21/87, is required with installation in accordance with Drawing List F20-1043, Revision Y dated 12/23/86, or Supplement Revision Q dated 8/20/87, is required with installation in accordance with Drawing List F20-1043, Revision Z dated 6/17/87.
- This modification requires installation of STC SA5838SW.
- 3. The aircraft is not to be operated as a Transport Category aircraft when the electronics equipment installed by this STC is in operation.
- 4. Compatibility of this modification with other previously approved modifications must be determined by the installer.

The FAA will reissue the certificate in the name of the transferee and forward it to him. TRANSFER ENDORSEMENT Transfer the ownership of Supplemental Type Certificate Number			
		O (Name of transferee)	
		Address of transferee)	(Number and street)
	(City, State, and ZIP code)		
from (Name of grantor) (Print or type	;)		
(Address of grantor)	(Number and street)		
<u> </u>	(City, State, and ZIP code)		
Extent of Authority (if licensing a	agreement):		

Signature of grantor (In ink): ___